## City of San Antonio Bid Tabulation

Opened:	July 16, 2004		]	
For:	Annual Contract for Differential Component Parts & New & Rebuilt Exchange Units			
			Grande Truck Center	Austin Drive Train
A259-02		MkR	4562 IH-10 East	201 E. Anderson Lane
			San Antonio,	Austin,
Item	Description		TX 78219	TX
I.	Rockwell/Meritor Differential Component Parts			
A.	Parts			
1	Percent of discount offered		Cost + 20%	40%
2	Product identification (manufacturer)		Meritor	
3	Type of price schedule (dealer, jobber, etc.)		Dealer	
4 5	Price schedule number Date of price schedule		Current June-04	
6	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)		Cost	
B.	Manufacturer & Model Number: Rockwell RS19-145, Single Axle			
1	New Assembly		\$1,827.41	
				(w/exchange)
2	Rebuilt Exchange		\$1,444.84 Core Charge: \$500.00	
			Core Charge. \$500.00	(w/excriange)
C.	Specified Items			
D.	Labor rate to repair & overhaul Rockwell RS19-145, Single Axle (Seven (7) hours		\$32.00	\$65.00
II.	Eaton Differential Component Parts			
A.	Parts			
1	Percent of discount offered		Cost + 20%	40%
2	Product identification (manufacturer)		Eaton	
3	Type of price schedule (dealer, jobber, etc.)		Dealer	
4	Price schedule number		Current	
5	Date of price schedule		June-04	
6	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)		Cost	List
B. 1	New Assemblies Eaton/Spicer RS-402		\$1,286.69	\$1,762.55
•			Core Charge: \$500.00	
2	Eaton/Spicer DS-402		\$2,120.96	
			Core Charge: \$750.00	
C.	Specified Items			
D.	Specified Items			
E.	Labor rate to repair & overhaul Eaton/Spicer RS-402 (Seven (7) hours maximum)		\$32.00	\$65.00
F.	Labor rate to repair & overhaul Eaton/Spicer DS-402 (Seven (7) hours maximum)		\$32.00	\$65.00
			ψ32.00	ψ03.00
III.	Navistar International Differential Component Parts			
Α.	Parts			
1 2	Percent of discount offered		Cost + 20%	
3	Product identification (manufacturer) Type of price schedule (dealer, jobber, etc.)		Aftermarket Dealer	Navistar List
4	Price schedule number		N/A	PL-1001-4
5	Date of price schedule		June-04	
6	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)		Cost	List
B.	Manufacturer & Model Number: Navistar International N400			
1	New Assembly		\$4,189.56	
2	Rebuilt Exchange		Core Charge: \$900.00 \$3,200.00	
_			Core Charge: \$900.00	
C.	Specified Items			
D.	Labor rate to repair & overhaul Navistar International N400 (Seven (7) hours maximum)		\$32.00	\$65.00
IV.	Shop Labor Rate per Hour for Removal, Repair & Reinstallation of Units on Vehicles		\$48.00	·
١٧.				
	Delivery		2 Days	,
	Terms		2%-10	Net 30